

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.15**SOURCE INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** SIR-000057**Date Inspected:** 08-May-2007**Project Name:** SAS Superstructure**OSM Arrival Time:** 800**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1730**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**Quality Control Contact:** Xu Jun**Quality Control Present:** Yes No**Material transfer:** Yes No N/A**Sampled Items:** Yes No N/A**Stock Transfer:** Yes No N/A**OK to Cut:** Yes No N/A**Rebar Test Witness:** Yes No N/A**Delayed/Cancelled:** Yes No N/A**Other:** N/A**Bridge No:** 34-0006**Component:** N/A**Bid Item:** 52**Lot No:** N/A**Summary of Items Observed:**

The CALTRANS Quality Assurance (QA) Inspector, Alfredo Acuna was present to oversee quality control functions and production activities related to welding, testing and fabrication of ABF's mock-ups and close ribs at the Zhenhua Port Machinery Company (ZPMC) facility on Changxing Island for the San Francisco Oakland Bay Self Anchored Suspension Bridge.

The QA inspector observed approximately eighty (80) ZPMC shop personnel performing fabrication activities on elevation 77.000 (diaphragm 3B), elevation 89.000 (diaphragm 2C), elevation 114.000 (tower splice) at the ZPMC OBG workshop.

The QA inspector observed five (5) ZPMC shop personnel performing activities associated with the welding of the close rib (welding a test plate) at the close-rib Gantry submerged arc welding machine (SAW).

The QA inspector observed ZPMC, ABF, Inspectech and Bureau Veritas inspectors performing observations and inspections.

Summary of Conversations:

The QA inspector did not have any significant conversations on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

SOURCE INSPECTION REPORT

(Continued Page 2 of 2)

Inspected By: Acuna,Alfredo

Quality Assurance Inspector

Reviewed By: McClary,David

QA Reviewer